



MX4000 Multiplexer Programming from the KBD4000 Keyboard

HELPFUL TIPS FOR PELCO PRODUCTS

Tip No.: 98-3032

Date: December 7, 1998

Product Affected: KBD4000 Keyboard



CAUTION: When programming the MX4000 multiplexer from the KBD4000 keyboard, do NOT attempt to change the unit ID. Changing the unit ID from the keyboard will interrupt the keyboard communications to the multiplexer resulting in erratic multiplexer operation.

If the UNIT ID, in the ADVANCED SYSTEM SETUP menu, is inadvertently changed at the keyboard, an uncontrollable sequencing of unit ID numbers and loss of keyboard control will result. If this happens, the following remedies are recommended:

- a. Go to the multiplexer front panel and press the down arrow button. The sequencing should stop. Exit the menu, then return to the ADVANCED SYSTEM SETUP menu and change the UNIT ID back to the correct multiplexer unit ID number. Continue normal programming from the keyboard.

OR

- b. If the multiplexer is remotely located away from the keyboard, wait until the numbers sequence to the correct multiplexer unit ID number and **immediately** move the joystick in any direction. The sequencing should stop. Continue normal programming from the keyboard.